

Table 1

Boat	Owner	Moor	Condition report
Aragorn	Steve Simmons	23	Checked March 25 SS reported good condition
Aspirations	Andy Charkzuk	21	
Atlanta	Oscar Bennet	7	3/4/25 HC GL SS dictaphone audio partially lost. New top unit likely needed before next season.
Beryl	John Williams	15	
Blyth Spirit	Patrick Lyndon-Stanford	N11	
Breakaway	Thomas Moy	3	3/4/25 HC GL SS yellow hard buoy. Upper riser needs replacement. Lower riser satisfactory thickness with some welded links. Has lower swivel at bottom seized. Recommend complete refurb.
Broadsword	Lawrence Newing	N8	
Cape Cod	Mark Harris	N6	
Catherine 2	John Knight	57	
Charlie Boy	Kyle Sanders	29	25/2/25 raft SS and RB complete all new refurb to sinker chain with h/d lower riser.
Colanna	Brooke Lyndon-Stanford	27	3/4/25 HC GL SS Yellow hippo buoy. Needs new top unit. Lower riser sound. Lower shackle checked by feel, appears sound.
Darwin	Jeff Lillington	43	
Daydream	Nicholas Funnell	82	
Enliven	Phil Taylor	85	
Samara	Lewis Stoop	N1	
Foreness	Michael Frankish	92	3/4/25 HC GI SS. Yellow,buoy Several metres uppers Good chain visible unable to assess buried chain.
Fulmar	Myles Stewart	60	
Girouette	Ken Grimes	44	
Gloria	Nick Donaldson	48	3/4/25 HC GL SS dictaphone message lost. From memory good! Please confirm.
INKONK	Vernon Leese	80	5/3/25 O/b single mooring line with single white pick up buoy Long rise chain split 3. Top 1m long top 2portions less than 10%wear . Lower riser heavier chain. Bottom sh not found. GL from bb
Janet	Wayne Colclough	66	
Jeddo	Dave Metcalfe	N2.	10/4/25 D.M Raft with H/C assist Checked to sinker.replaced 26mm Shackle between riser and ground chain Added additional shackle to 3rd link to bypass worn links. Buoy has damage from top shackle, but doesn't seem to have affected buoyancy.
Jess	Rob Jones	36	
Karaway	Melvyn Worrell	59	
Kia Kia	Lou M-W	28	3/4/25. HC GL SS. No dictaphone audio. From memory generally sound.
Kingfisher 10	Peter Peek	1	3/4/25 HC GL SS. Yellow hard buoy. Bird's nest of chain at bottom due to previous cutaways.. Upper riser 50% worn . Recommend complete refurb.
Lady of Leisure	Philip Minoudis	90	3/4/25 HC GL SS . Orange buoy requires top plate. Good admiralty chain on surface Good riser to buoy but worn within buoy recommend changing top chain or shortening and adding top plate within 1 year. . But shackle and swivel undone top connected to bottom by rope only. Did not have shackle aboard so will need fixing before boat attached.

Lethera	Ken Milburn	94	check as far as possible- appears to be acceptable some wear noted in main riser chain approximately 1-2 metres above ground tackle , riser above swivel good. @15mm min. 28/3/25 KM
Marie Louise	Graham Osborne	58	
Micawber	Chris Morgan	24	
Molly Coddle	Charles Adams	70	
Moksha	Ravinder Rana	17	
Necora /Raven	Paul Taylor	18	
Nereides 3	Frank Knight	64	
Nimrod	Ivor Morgan	N9	
Pandemonium	Dave Allen	14	3/4/25 HC GL SS. Lower riser laying under boat unable to assess. Upper riser some wear likely to need replacing by next season.. One of two mooring lines severely frayed breakage imminent.. other sound.
Papillon 2	Roger Bromley	88	
Pegasus	Nigel Thomas	81	
Pugwash	Charlie Adams?	71	
Pyewacket	Andy Wooten	93	March 25 Raft. SS Upper check reported good
Moonwind	David Wright	N5	
Red Dwarf			
Revival	Joe Robinson/Sultan Khan	91	
Romany	Roy Marley	35	
Rhiannon	Geoff Coote	16	
Shearwater	Graham Leighton	N4	
	Chris Main	N10	
Solstice	Garth Sonley	34	
Sparky	Jim Jupp	12	
Susie Q	Bill Strefford	69	
Tahoe Zephyr	Ricky Barnes	89	3/4/25 HC GL SS . Yellow cone buoy. Boat in situ. Good quality upper riser. Quite short. Lower riser buried gloopy mud not possible, to check properly but Checked to sinker 6/5/22. New 24mm lower riser, swivel upper riser.
Tiki	Ralph Burkinshaw	2	
Wheatear	Paul Mesher	N3	3/4/25 HC GL SS. Some wear in top chain. Replace at leisure
Windana	Mike Snarr	45	
			Vacant moorings
		V/E	

